

Final Reclamation and Stormwater Inspection

Date: 01/31/2025

Operator: HOUSTON EXPLORATION COMPANY* THE
- 10068

Location ID: 411455

Inspection Document #: 718700037

Yuma County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 1. Taken near the start of the access road. It does not appear that the access road has been reclaimed with evidence of non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 2. Taken along the access road. It does not appear that the access road has been reclaimed with evidence of non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 3. Taken along the access road. Red dotted line illustrates that a portion of the access road does not appear to have been recontoured to reflect adjacent topography.

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 4. Taken along the access road. It does not appear that the access road has been reclaimed with evidence of non-uniform vegetation cover resulting in bare soil.

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 5. Taken near the southwest corner of the former location. It appears that the former well location is progressing towards reclamation standards and regulations with desirable vegetation observed.

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 6. Taken near the northwest corner of the former location. Portions of the location are experiencing non-uniform vegetation cover resulting in areas of bare/exposed soils.

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 7. Taken near the northeast corner of the former location. It appears that the former location is progressing towards reclamation standards and regulations with desirable vegetation observed.

Inspection Photos
Location Name: Bledsoe 9-17-3-34
Location ID: 411455



Photo 8. Taken near the southeast corner of the former location. It appears that the former location is progressing towards reclamation standards and regulations with desirable vegetation observed.