

Final Reclamation and Stormwater Inspection

Date: 01/31/2025

Operator: HOUSTON EXPLORATION COMPANY* THE
- 10068

Location ID: 411471

Inspection Document #: 718700038

Yuma County, CO



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Bledsoe 1-31-3-43
Location ID: 411471



Photo 1. Taken from the start of the reclaimed access road. The access road appears to meet Rule 1004 standards and regulations and is reflective of the adjacent reference areas.

Inspection Photos
Location Name: Bledsoe 1-31-3-43
Location ID: 411471



Photo 2. Taken from the mid point of the reclaimed access road; see comments in Photo 1.

Inspection Photos
Location Name: Bledsoe 1-31-3-43
Location ID: 411471



Photo 3. Taken near Well API 125-09174. It does not appear that the location is progressing towards Rule 1004 standards and regulations with evidence of non-uniform vegetation cover resulting in bare/exposed soils. Additional reclamation activities are required.

Inspection Photos
Location Name: Bledsoe 1-31-3-43
Location ID: 411471



Photo 4. Taken from the southeastern portion of the location, facing north. See comments in Photo 3 for additional information.

Inspection Photos
Location Name: Bledsoe 1-31-3-43
Location ID: 411471



Photo 4. Taken from the western portion of the location, facing east. See comments in Photo 3 for additional information.

Inspection Photos
Location Name: Bledsoe 1-31-3-43
Location ID: 411471



Photo 6. Taken from the northern portion of the location, facing southwest. See comments in Photo 3 for additional information.

Inspection Photos
Location Name: Bledsoe 1-31-3-43
Location ID: 411471



Photo 7. Adjacent reference area southwest of the former location.