

# Inspection Photos

Loc: 472992

Operator: KODA EXPLORATION LLC

Inspection Date: 2/4/2025

County: LINCOLN



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing east at the access road off the county road. The fence needs to be reinstalled back to the original position. The gravel needs to be removed and road reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:472992 | Date: 2/4/2025

## Inspection Photos



**Photo 2.** Further east along the road perennial vegetation appears to be growing back into the former road.



## Inspection Photos



**Photo 3.** Drone aerial photo facing east along the former access road. The two track road further along appears to be in use and not reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:472992 | Date: 2/4/2025

## Inspection Photos



**Photo 4.** Drone aerial photo facing northeast along the former access road.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:472992 | Date: 2/4/2025

## Inspection Photos



**Photo 5.** Drone aerial photo facing north toward the location.




**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:472992 | Date: 2/4/2025

## Inspection Photos



**Photo 6.** Drone aerial photo facing north toward the location. It appears perennial vegetation is progressing in most areas of the location.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:472992 | Date: 2/4/2025

## Inspection Photos



**Photo 7.** Drone aerial photo facing west at the location. There are areas that should be seeded to promote more vegetation growth.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:472992 | Date: 2/4/2025