

Inspection Photos

Feburary 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 311996

Inspection Document #: 714001772

La Plata County, CO

Township: NESE 21 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Groff A2, 4
Location ID: 311996



Photo 1. View of the well pad from the access point facing center.



Inspection Photos
Location Name: Groff A2, 4
Location ID: 311996

2/3/25
268° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo: Perimeter fence has been repaired.

API #: 067-0364, 09434

Inspection Photos
Location Name: Groff A2, 4
Location ID: 311996

2/3/25
213° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Produced water tank label has deteriorated and is no longer displaying tank capacity.

API #: 067-0364, 09434

Inspection Photos
Location Name: Groff A2, 4
Location ID: 311996



Photo 4. Stained soils observed at well head #2.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-0364, 09434

Inspection Photos
Location Name: Groff A2, 4
Location ID: 311996

2/3/25
246° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Western interim reclamation area composed of Crested Wheatgrass, Sand Dropseed and Western Wheatgrass.

API #: 067-0364, 09434

Inspection Photos
Location Name: Groff A2, 4
Location ID: 311996

2/3/25
96° E



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. Active cow pasture reference area, vegetation composed of grazed Intermediate Wheatgrass.

API #: 067-0364, 09434