

TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819



No sign at wellhead



Debris

TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819



Out of Service




Missing required labeling

TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819



Out of Service



Missing required labeling

TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819



Open end gas supply valve




Open end gas supply valve

TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819



Debris



Open end ethylene glycol drain valves

TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819



Staining



Staining

TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819



Open end ethylene glycol drain valve



Debris

**TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819**



Debris



Location from Southwest corner and entrance

**TEP Rocky Mountain LLC
Federal RGU 31-25-198
Location ID: 416819**



Location from North corner



Location from East corner