

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404083723

Date Received:
02/06/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001674

Inspection Date: 01/07/2025

FIR Submit Date: 01/09/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 325048

Location Name: SNOOKS GAS UNIT "A"- N32N7W Number: 7NENE County: _____

Qtrqr: NENE Sec: 7 Twp: 32N Range: 7W Meridian: N

Latitude: 37.036381 Longitude: -107.644951

FACILITY - API Number: 05-067- -00 Facility ID: 325048

Facility Name: SNOOKS GAS UNIT "A"- N32N7W Number: 7NENE

Qtrqr: NENE Sec: 7 Twp: 32N Range: 7W Meridian: N

Latitude: 37.036381 Longitude: -107.644951

CORRECTIVE ACTIONS:

1 CA# 201585

Corrective Action: Comply with rule 606, remove and properly dispose of weedy debris.

Date: _____

Response: CA COMPLETED

Date of Completion: 02/04/2025

Operator
Comment:

Weeds removed.

ECMC Decision: _____

Date:

Date of Completion: 02/04/2025

Eroding berm rebuilt.

ECMC Decision:

--

Corrective actions completed. See attachment for photos.

Signed: _____

Date: 2/6/2025 8:15:46 AM

404083723	FIR RESOLUTION SUBMITTED
404083732	Snook A1 completion photos

Page 2 of 2