

Inspection Photos

Loc: 431589

Operator: PIONEER NATURAL RESOURCES USA INC

Inspection Date: 2/4/2025

County: LINCOLN



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 2. Drone aerial photo facing south along the access road. The former access road has not established perennial vegetation and needs to be reseeded.



Inspection Photos




Photo 2. Drone aerial phot facing south toward the location. Perennial vegetation has not established. Additional reseeding needs to be performed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing down toward the ground cover shows almost entirely bare soils. Additional reseeding needs to be performed.



Inspection Photos



Photo 4. East side of the location facing west.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:431589 | Date: 2/4/2025

Inspection Photos




Photo 5. Facing southeast toward the reference area which consists of native Blue grama dominate grassland.



Inspection Photos



Photo 6. Facing east toward the surrounding undisturbed pasture.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Loc:431589 | Date: 2/4/2025