

Inspection Photos

February 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 334192

Inspection Document #: 714001777

La Plata County, CO

Township: SWSW 10 34N 9W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Linder Slatin A2, A4
Location ID: 334192



Photo 1. View of the well pad from the access point facing center.

2/3/25
105° E



Inspection Photos
Location Name: Linder Slatin A2, A4
Location ID: 334192



Photo 3. Stained soil at wellhead # 4.

2/3/25
344° N



Inspection Photos
Location Name: Linder Slatin A2, A4
Location ID: 334192



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Western Interim reclamation area composed of Western Wheatgrass and Sand Dropseed.

API #: 067-08950, 09336

Inspection Photos
Location Name: Linder Slatin A2, A4
Location ID: 334192



Photo 6. View of Musk Thistle along access road. Evidence that thistle had flowered and gone to seed this season.



Photo 7. Reference area composed of Smooth Brome and Prairie Sunflower.