

Inspection Photos

February 3rd, 2024

Operator: Simcoe LLC - 10749

Location ID: 325798

Inspection Document #: 714001780

La Plata County, CO

Township: SENW 9 34N 8W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Sally Jo Lorret A1
Location ID: 325798




Photo 1. View of the well pad from the access point facing center.

Inspection Photos
Location Name: Sally Jo Lorret A1
Location ID: 325798



Inspection Photos
Location Name: Sally Jo Lorret A1
Location ID: 325798

2/3/25
333° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Western interim reclamation area composed of Smooth Brome, Sand Dropseed and Rabbitbrush.

API #: 067-07002



Inspection Photos
Location Name: Sally Jo Lorret A1
Location ID: 325798



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Crested Wheatgrass, Sagebrush and Juniper.

API #: 067-07002