

Inspection Photos

02/05/2025

Operator: CAERUS PICEANCE LLC #10456

Location ID: 312527

Inspection Doc: 718100252

Mesa County, CO

Aaron Trujillo
Western Reclamation Work Lead
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 312527



Photo 1: Photos 1-2 taken from the Location. Photos provide an overview of the Location from North, East, South to West.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 312527



Photo 2: See comments under photo 1.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 312527



Photo 3: Photos 3-4 taken from the reference areas. Photos provide an overview of the reference area for comparison to the reclaimed areas, from North, East, South to West.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location ID: 312527



Photo 4: See comments under photo 3.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources