

# Inspection Photos

02/05/2025

**Operator:** LARAMIE ENERGY LLC - 10433

**Location ID:** 312635

**Inspection Doc:** 718100258

Mesa County, CO

Aaron Trujillo

Western Reclamation Work Lead

ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 1:** Photos taken from the east end of the (fenced) Location. Photos provide an overview of the Location from south, southwest, northwest to north.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 2:** See comments under photo 1.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 3:** Signage on east end of the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 4:** Photos taken from the northwest end of the Location, facing northeast and east. Photos provide an overview of the fenced pit/remediation areas. Photos also shows pipe equipment being stored on the northwest end of the Location. Evidence of vehicles/equipment traveling within the reclamation areas observed.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 5:** Photo shows pit/excavation associated with spill #488131. Photo also shows water within the pit. Water is possibly groundwater.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 6:** Photo example of the re-disturbed areas adjacent to the pit.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 7:** Photos examples of various trash/debris or unused equipment/materials improperly placed on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 8:** Photos examples of various trash/debris or unused equipment/materials improperly stored on the Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 9:** Photos 9-11 examples showing that the Location is predominantly bare and exposed soil; germination and establishment of desirable perennial species was not observed and/or not progressing towards ECMC uniform requirements. Photos also show mulch applied to Location is no longer functioning, and erosion, degradation and sediment transport was observed. Photo right also shows what appears to be vehicle/equipment ruts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 10:** See comments under photo 9. Photos also show stormwater and erosion control BMPs are missing or insufficient; erosion, degradation and sediment transport evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



February 5, 2025



February 5, 2025

**Photo 11:** See comments under photo 9. Photos also show stormwater and erosion control BMPs are missing or insufficient; erosion, degradation and sediment transport evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



February 5, 2025



February 5, 2025

**Photo 12:** See comments under photo 9. Photos also show stormwater and erosion control BMPs are missing or insufficient; erosion, degradation and sediment transport evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 13:** See comments under photo 9. Photos also show stormwater and erosion control BMPs are missing or insufficient; erosion, degradation and sediment transport evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 14:** Photos taken from the southern perimeter of the Location. Photos examples showing erosion logs are no longer in proper functioning condition. Stormwater and erosion control BMPs are missing or insufficient; erosion, degradation and sediment transport evident.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



February 5, 2025



February 5, 2025

**Photo 15:** See comments under photo 14.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



February 5, 2025



February 5, 2025

**Photo 16:** Photos taken from the southern areas of the Location; these areas appear to have been traveled over by equipment. Photo shows soils have within these areas have been compacted.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 17:** Photos taken from the Location entrance. Photos show these areas were not reclaimed during initial reclamation efforts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312635



**Photo 18:** Photos taken from the location entrance, on the east end of the Location. These areas do not appear to have been included during initial reclamation efforts.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources