

# Inspection Photos

02/05/2025

**Operator:** LARAMIE ENERGY LLC - 10433

**Location ID:** 312637

**Inspection Doc:** 718100260

Mesa County, CO

Aaron Trujillo  
Western Reclamation Work Lead  
ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312637



**Photo 1:** Signage at access road.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312637



**Photo 2:** Photos 2-3 taken from the central areas of the Location. Photos provide an overview of the reclamation from north, east, south to west. Vegetation within the central areas of the Location is predominantly weedy species (Russian thistle), though perennial grass establishment is evident within the weeds. Grasses will likely outcompete weeds in a few more years.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312637



**Photo 3:** See comments under photo 2.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: LARAMIE ENERGY LLC - 10433

Location ID: 312637



**Photo 4:** Photo example of the reference areas for comparison.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources