

Inspection/Audit Photos  
Location: CHEVRON USA INC  
SKINNER RIDGE-66S98W/11SESE (SKINNER RIDGE #698-11-1)  
Location ID: 324305  
Date: 02/4/2025



Feb 4, 2025 at 11:57:12 AM  
+39.542387,-108.291881 ±13.86m



Feb 4, 2025 at 11:57:40 AM  
+39.542959,-108.291924 ±2.67m

Photo # 4038 Entrance to location

Photo # 4035 Location

Inspection/Audit Photos  
Location: CHEVRON USA INC  
SKINNER RIDGE-66S98W/11SESE (SKINNER RIDGE #698-11-1)  
Location ID: 324305  
Date: 02/4/2025



Photo # 4039 Location



Photo # 4046 Location

Inspection/Audit Photos  
Location: CHEVRON USA INC  
SKINNER RIDGE-66S98W/11SESE (SKINNER RIDGE #698-11-1)  
Location ID: 324305  
Date: 02/4/2025



Photo # 4054 Location



Photo # 4058 Location

Inspection/Audit Photos  
Location: CHEVRON USA INC  
SKINNER RIDGE-66S98W/11SESE (SKINNER RIDGE #698-11-1)  
Location ID: 324305  
Date: 02/4/2025



Photo # 4064 NW corner of location



Photo # 4065 SW corner of location

Inspection/Audit Photos  
Location: CHEVRON USA INC  
SKINNER RIDGE-66S98W/11SESE (SKINNER RIDGE #698-11-1)  
Location ID: 324305  
Date: 02/4/2025



Photo # 4067 SE corner of location

Photo # 4068 NE corner of location

Inspection/Audit Photos  
Location: CHEVRON USA INC  
SKINNER RIDGE-66S98W/11SESE (SKINNER RIDGE #698-11-1)  
Location ID: 324305  
Date: 02/4/2025



Photo # 4074 Unmarked Deadman