

Inspection Photos

Loc: 307822

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/6/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing north at the location. The water level was above freeboard.



Inspection Photos



Photo 2. Facing east along the fill slope which is stabilized with vegetation.

