

# Inspection Photos

Loc: 308808

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 2/6/2025

County: LAS ANIMAS



Inspection Photos



**Photo 1.** Facing northwest at the location. Door on meter shed was left open.



Inspection Photos



**Photo 2.** Facing north toward the wellsite.



Inspection Photos



**Photo 3.** Facing north along the fill slope which is stabilized with vegetation.



## Inspection Photos



**Photo 4.** There is some oily fluid in the engine skid that will need to be cleaned up..

