

# Inspection Photos

Loc: 307662

Operator: EVERGREEN NATURAL  
RESOURCES LLC

Inspection Date: 2/6/2025

County: LAS ANIMAS



Inspection Photos



**Photo 1.** Facing north at the location. Well sign is posted on meter shed..



Inspection Photos



February 6, 2025  
+37.142194,-104.658534  
Las Animas County  
ECMC

**Photo 2.** Facing east toward the wellsite.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

Loc:307662 | Date: 2/6/2025

Inspection Photos



**Photo 3.** Facing north along the fill slope which is stabilized with vegetation.



Inspection Photos



**Photo 4.** Facing south toward the PW pit which fenced in.

