

Inspection Photos
Location Name: Day 12-35
API Number: 125-08826



1. Lease sign at well location.



2. View of wellhead.

Inspection Photos
Location Name: Day 12-35
API Number: 125-08826




3. Burrows inside wellhead fencing.



4. Well location overview.

Inspection Photos
Location Name: Day 12-35
API Number: 125-08826



5. Lease sign at shared gathering location.



6. Gas meter inside meter shed.