

Inspection Photos  
Location Name: Eyestone 5-35  
API Number: 125-08706



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Eyestone 5-35**  
**API Number: 125-08706**



**3. View of release location at wellhead. Note absence of fine sand at release point.**



**4. View of leaking check valve. Note salt staining on check valve body.**



Inspection Photos  
Location Name: Eystone 5-35  
API Number: 125-08706



5. Well location overview.



6. Lease sign at gathering location.

**Inspection Photos**  
**Location Name: Eyestone 5-35**  
**API Number: 125-08706**



**7. Gas meter inside meter shed. Note roof damage at top of frame.**



**8. Gathering location overview.**