

Inspection Photos  
Location Name: Day 33-35 4N47W  
API Number: 125-10975



1. Lease sign at well location.



2. View of wellhead.

**Inspection Photos**  
**Location Name: Day 33-35 4N47W**  
**API Number: 125-10975**




**3. View of stubbed up electrical line inside black poly line.**



**4. Well location overview.**

Inspection Photos  
Location Name: Day 33-35 4N47W  
API Number: 125-10975



5. Lease sign at gathering location.



6. Gas meter inside meter shed.