

## State of Colorado

## Energy &amp; Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404082887

Date Received:

02/10/2025

Spill report taken by:

NEIDEL, KRIS

Spill/Release Point ID:

489200

## SPILL/RELEASE REPORT (SUPPLEMENTAL)

This form is to be submitted by the party responsible for the oil and gas spill or release. Refer to ECMC Rule 912.b. for reporting requirements of spills or releases of E&P Waste, produced Fluids, or unauthorized Releases of natural gas. Submit a Site Investigation and Remediation Workplan (Form 27) if Rule 913.c. applies.

## OPERATOR INFORMATION

Name of Operator: WEXPRO COMPANY	Operator No: 95960	<b>Phone Numbers</b> Phone: (307) 3715695 Mobile: (307) 3715695 Email: russell.l.ferrell@dominienergy.com
Address: P O BOX 45003		
City: SALT LAKE CITY	State: UT Zip: 84145-0601	
Contact Person: Russell Ferrell		

☐ Transfer of Operatorship: Pursuant to Rule 912.f, this Supplemental Form 19 is being submitted to designate the Buying Operator as the responsible Operator for this Spill and Release.

## INITIAL SPILL/RELEASE REPORT

Initial Spill/Release Report Doc# 404073576

Initial Report Date: 01/29/2025 Date of Discovery: 01/28/2025 Spill Type: Recent Spill

**Spill/Release Point Location:**

QTRQTR Lot 5 SEC 5 TWP 11N RNG 97W MERIDIAN 6

Latitude: 40.946300 Longitude: -108.310120

Municipality (if within municipal boundaries): County: MOFFAT

Enter Lat./long measurement of the actual Spill/Release Point. Lat./Long. Data shall meet standards of Rule 216.

☐ Check this box if this spill/release is related to a loss of integrity of a flowline, pipeline, crude oil transfer line, or produced water transfer line.

**Reference Location:**

Facility Type: PIPELINE

☐ Facility/Location ID No

Spill/Release Point Name: Powder Wash Camp Lateral 118

☐ Well API No. (Only if the reference facility is well) 05- -☒ No Existing Facility or Location ID No.

Estimated Total Spill Volume: use same ranges as others for values

Estimated Oil Spill Volume(bbl): 0

Estimated Condensate Spill Volume(bbl): 0

Estimated Flow Back Fluid Spill Volume(bbl): 0

Estimated Produced Water Spill Volume(bbl): &gt;=1 and &lt;5

Estimated Other E&amp;P Waste Spill Volume(bbl): 0

Estimated Drilling Fluid Spill Volume(bbl): 0

Specify: Spill was production fluids

Has the subject Spill/Release been controlled at the time of reporting? Yes

**Land Use:**

Current Land Use: NON-CROP LAND

Other(Specify): Oil and gas facilities

Weather Condition: Sunny and not windy.

Surface Owner: FEDERAL

Other(Specify): BLM

Describe what is known about the spill/release event (what happened -- including how it was stopped, contained, and recovered):

At 5:05 PM on January 28 a 3rd party operator notified Wexpro of a production gathering lateral failure approximately 150 yards from Wexpro's Powder Wash field office. Wexpro operators had left for the day at 4 PM and the leak was not occurring at this time. Operations mobilized to the field and isolated the leak approximately an hour after notification. Production fluids were observed to have surfaced at the leak location and run downhill over frozen ground for roughly 40 yards. No waterways were impacted.

**List of Agencies and Other Parties Notified Pursuant to Rule 912.b.(7)-(11):**

**OTHER NOTIFICATIONS**

Date	Agency/Party	Contact	Phone	Response
1/29/2025	BLM	James Roberts	-	notified via email @ j75rober@blm.gov
1/29/2025	CPW	Taylor Elm	-	notified via email @ taylor.elm@state.co.us
1/29/2025	Moffat County	Jeff Comstock	-	notified via email @ jcomstock@moffatcounty.net

**REPORT CRITERIA**

**Rule 912.b.(1) Report to the Director (select all criteria that apply):**

No Rule 912.b.(1).A: A Spill or Release of any size that impacts or threatens to impact any Waters of the State, Public Water System, residence or occupied structure, livestock, wildlife, or publicly-maintained road.

Waters of the State: \_\_\_\_\_ Public Water System: \_\_\_\_\_  
Residence or Occupied Structure: \_\_\_\_\_ Livestock: \_\_\_\_\_  
Wildlife: \_\_\_\_\_ Publicly-Maintained Road: \_\_\_\_\_

Yes Rule 912.b.(1).B: A Spill or Release in which 1 barrel or more of E&P Waste or produced fluids is spilled or released outside of berms or other secondary containment.

No Rule 912.b.(1).C: A Spill or Release of 5 barrels or more of E&P Waste or produced Fluids regardless of whether the Spill or Release is completely contained within berms or other secondary containment.

No Rule 912.b.(1).D: Within 6 hours of discovery, a Grade 1 Gas Leak. For a Grade 1 Gas Leak from a Flowline, the Operator also must submit the Form 19 – Initial, document number on a Form 44, Flowline Report, for the Grade 1 Gas Leak

Enter the approximate time of discovery \_\_\_\_\_ (HH:MM)  
Enter the Document Number of the Grade 1 Gas Leak Report, Form 44 \_\_\_\_\_  
Was there a reportable accident associated with either a Grade 1 Gas Leak or an E&P waste spill or release? \_\_\_\_\_  
Enter the Document Number of the Initial Accident Report, Form 22 \_\_\_\_\_  
Was there damage during excavation? \_\_\_\_\_  
Was CO 811 notified prior to excavation? \_\_\_\_\_

No Rule 912.b.(1).E: The discovery of 10 cubic yards or more of impacted material resulting from a current or historic Spill or Release. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards.

Estimated Volume of Impacted Solids (cu. yd.): \_\_\_\_\_

No Rule 912.b.(1).F: The discovery of impacted Waters of the State, including Groundwater. Discovery and reporting will not be contingent upon confirmation samples demonstrating exceedance of Table 915-1 standards. The presence of free product or hydrocarbon sheen on Groundwater or surface water is reportable. The presence of contaminated soil in contact with Groundwater or surface water is reportable. Check all that apply:

- ☐ The presence of free product or hydrocarbon sheen Surface Water  
☐ The presence of free product or hydrocarbon sheen on Groundwater  
☐ The presence of contaminated soil in contact with Groundwater  
☐ The presence of contaminated soil in contact with Surface water

No	Rule 912.b.(1).G: A suspected or actual Spill or Release of any volume where the volume cannot be immediately determined, including a spill or release of any volume that daylights from the subsurface.
No	Rule 912.b.(1).H: Spill or Release resulting in vaporized hydrocarbon mists that leave the Oil and Gas Location or Off-Location Flowline right of way from an Oil and Gas Location and impacts or threatens to impact off-location property.
	<input type="checkbox"/> Areas offsite of Oil & Gas Location <input type="checkbox"/> Off-Location Flowline right of way
No	Rule 912.b.(1).I: A Release of natural gas that results in an accumulation of soil gas or gas seeps.
No	Rule 912.b.(1).J: A Release that results in natural gas in Groundwater.

## SPILL/RELEASE DETAIL REPORTS

#1	Supplemental Report Date: 02/06/2025		
<b>FLUIDS</b>	BBL's SPILLED	BBL's RECOVERED	Unknown
OIL	0	0	<input type="checkbox"/>
CONDENSATE	0	0	<input type="checkbox"/>
PRODUCED WATER	3	3	<input type="checkbox"/>
DRILLING FLUID	0	0	<input type="checkbox"/>
FLOW BACK FLUID	0	0	<input type="checkbox"/>
OTHER E&P WASTE	0	0	<input type="checkbox"/>
specify: production fluids			
Was spill/release completely contained within berms or secondary containment? NO Was an Emergency Pit constructed? NO			
Secondary containment, <b>including walls &amp; floor regardless of construction material</b> , must be sufficiently impervious to contain any discharge from primary containment until cleanup occurs.			
<b>A Form 15 Pit Report shall be submitted within 30 calendar days after the construction of an emergency pit</b>			
Impacted Media (Check all that apply) <input checked="" type="checkbox"/> Soil <input type="checkbox"/> Groundwater <input type="checkbox"/> Surface Water <input type="checkbox"/> Dry Drainage Feature			
Surface Area Impacted: Length of Impact (feet): 25		Width of Impact (feet): 8	
Depth of Impact (feet BGS): 6		Depth of Impact (inches BGS):	
How was extent determined?			
Extent was determined through visual inspection. Samples are being taken to learn more of the extent of the impacts.			
Soil/Geology Description:			
Tresano-hiatha-kandaly			
Depth to Groundwater (feet BGS) 1000		Number Water Wells within 1/2 mile radius: 3	
If less than 1 mile, distance in feet to nearest	Water Well 257	None <input type="checkbox"/>	Surface Water 1492
	Wetlands	None <input checked="" type="checkbox"/>	Springs
	Livestock	None <input checked="" type="checkbox"/>	Occupied Building
Additional Spill Details Not Provided Above:			
Wexpro company is working to repair the damaged gathering line. The spill area has been excavated and samples are being taken. All free liquids were recovered with a hydro vac.			

## REQUEST FOR CLOSURE

**Spill/Release Reports should be closed when impacts have been remediated or when further investigation and corrective actions will take place under an approved Form 27.**

Basis for Closure: ☐ Corrective Actions Completed (documentation attached, check all that apply)

☐ Horizontal and Vertical extents of impacts have been delineated.

☐ Documentation of compliance with Table 915-1 is attached.

☐ All E&P Waste has been properly treated or disposed.

☐ Work proceeding under an approved Form 27 (Rule 912.c).

Form 27 Remediation Project No: \_\_\_\_\_

☐ SUSPECTED Spill/Release did not occur or was below Rule 912.a.(5) reporting thresholds.

### OPERATOR COMMENTS:

Wexpro company is working to repair the damaged gathering line. The spill area has been excavated and samples are being taken. All free liquids were recovered with a hydro vac.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Russell Ferrell

Title: Assoc. Reclamation Agent Date: 02/10/2025 Email: russell.l.ferrell@dominionenergy.com

<u>COA Type</u>	<u>Description</u>
-----------------	--------------------

0 COA	

### ATTACHMENT LIST

<u>Att Doc Num</u>	<u>Name</u>
404082934	OTHER
404082938	AERIAL IMAGE
404082945	PHOTO DOCUMENTATION

Total Attach: 3 Files

### General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)