

Inspection Photos

February 7th, 2024

Operator: Seeley Oil Company - 10506

Location ID: 322117

Inspection Document #: 714001797

Dolores County, CO

Township: SENE 23 38N 20W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Canyon 1
Location ID: 322117

2/7/25
171° S



2/7/25
157° SE



Photo 1. View of the well pad from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 033-06116

Inspection Photos
Location Name: Canyon 1
Location ID: 322117

2/7/25
314° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2: Northern interim reclamation area composed of Sagebrush, Rabbitbrush, Broom Snakeweed and Prairie Sunflower.

API #: 033-06116

2/7/25
81° E



Photo 3. Labels at shed/separator equipment are starting to deteriorate, future maintenance advised.

Inspection Photos
Location Name: Canyon 1
Location ID: 322117

2/7/25
242° SW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Sagebrush, Rabbitbrush, Juniper and Broom Snakeweed.

API #: 033-06116