

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 2/6/2025



Location Overview – Photo #06501



Location – Photo #06502

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 2/6/2025



Feb 6, 2025 at 11:49:44
Parachute CO 81635
United States

Location – Photo #06503



Feb 6, 2025 at 11:51:08
Parachute CO 81635
United States

Location – Photo #06505

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 2/6/2025



Location – Photo #06506



Location – Photo #06504

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 2/6/2025



Location – Photo #06508



Cut Slope Eroding onto Access Road – Photo #06509

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/PA 22-21

Location ID: 417668

Date: 2/6/2025



Cut Slope Eroding onto Access Road – Photo #06510