

*Harpoon Teardown Report

Sent By

Sent At

Submitted By:

Weather:

Report # (Serial Number, Setup Number, T for Teardown) ie. H15P-012 J5 T:

Customer:

Field Contact:

Phone #:

Supervisor Name:

Lease Name:

State/Province:

Tank Size:

Tear Down Start Time:

 

Fluid Composition:

Tear Down Finish Time:

 

Equipment Type:

Lifting Implements Serial #:

09-12

Lifting Implements Visually Inspected?:

☒ Yes ☐ No

Equipment Used:

Tank Panels Serial #:

H20p-04

Tank Panels Visually Inspected?:

☒ Yes ☐ No

Are Panels/links Damaged?:

☐ Yes ☒ No

Tank Panels Properly Removed?:

☒ Yes ☐ No





Liner Serial #:

Liner Visually Inspected?:

☒ Yes ☐ No

Liner Visually Inspected for cleanliness?

☒ Yes ☐ No

Is Liner Damaged?:

☐ Yes ☒ No



Liner Properly Removed and Folded for Transport?:

☒ Yes ☐ No



Comments:

Groundcloth Visually Inspected?:

☒ Yes ☐ No

Groundcloth Properly Removed?:

☒ Yes ☐ No

HYDRM Serial Number and Sensors Recovered:

HYDRM27

- ☐ Manifold Pressure Sensor
- ☒ Tank Floor Pressure Sensor
- ☒ Antenna
- ☐ Ultrasonic Level Sensor
- ☒ Temperature Sensor
- ☒ Auxiliary Solar Panel

Upload Photo of HYDRM System Upon Arrival:

Manifold Set Serial #:

008

Manifold Set Visually Inspected?:

☒ Yes ☐ No

Is Manifold Set Missing Parts or Damaged?

☐ Yes ☒ No

Manifolds Properly Removed and Drained?:

☒ Yes ☐ No



Additional Items Removed?:

Additional Items Removed Not Listed:

Third Party Vendors?:

☒ Yes ☐ No

Service:

Vendor:

Quantity:

Hours on Location:

General Project Comments:

Signed on

Corfix

X _____

Signed _____