

Inspection Photos
Location Name: Jack C. Noel Unit #2
Location ID: 318645



Photo 1: Damages, unlegible Wellhead Sign

Photo 2: Wellhead. Debris, dead vegetation