

Interim Reclamation and Stormwater Inspection

January 31, 2025

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 311299

Well Name: WOOLLEY UNIT #1

Inspection Document #: 718600242

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: WOOLLEY UNIT #1
Location ID: 311299



Photo 1. Looking north across well location. It appears this electric box is associated with the Woolley Unit 1 well. Undesirable weeds Kochia and Russian Thistle are present on location.



Photo 2. The area east of the well appears to have reclamation activities performed.



Inspection Photos
Location Name: WOOLLEY UNIT #1
Location ID: 311299



Photo 3. Photo taken north of the wellhead. Trash (bags of leaves) is present on location.



Photo 4. Photo taken looking at the pumpjack. Undesirable weeds Kochia and Russian Thistle are present around the equipment.



Inspection Photos
Location Name: WOOLLEY UNIT #1
Location ID: 311299



Photo 5. Looking west from the well location.



Photo 6. Looking southwest down access road.

