

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 3-W-29

Location ID: 335238

Date: 2/10/2025



Location Overview – Photo #06537



Location – Photo #06540

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 3-W-29

Location ID: 335238

Date: 2/10/2025



Feb 10, 2025 at 14:11:01
Parachute CO 81635
United States



Feb 10, 2025 at 14:09:03
Parachute CO 81635
United States

Location – Photo #06547

Location – Photo #06543

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 3-W-29

Location ID: 335238

Date: 2/10/2025



Location – Photo #06546



Open Wellhead Cellar – Photo #06548

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 3-W-29

Location ID: 335238

Date: 2/10/2025



Fallen Wellhead Fencing – Photo #06541

Fallen Wellhead Fencing – Photo #06542

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, Federal/DOE 3-W-29

Location ID: 335238

Date: 2/10/2025



Stored Supplies – Photo #06539



Trash – Photo #06545