

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 2/11/2025



Location – Photo #06573



Location – Photo #06577



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 2/11/2025



Location – Photo #06583



Sediment Transported onto Access Road/No BMPs – Photo #06574



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 2/11/2025



**Sediment Transported onto Access Road/No BMPs – Photo #06575**



**Sediment Transported onto Access Road/No BMPs – Photo #06576**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 2/11/2025



**Sediment Transported onto Location – Photo #06579**



**Sediment Transported onto Location – Photo #06580**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PUCKETT-66S96W/32SWNW

Location ID: 335394

Date: 2/11/2025



**Sediment Transported onto Location – Photo #06581**



**Sediment Transported onto Location – Photo #06582**