

Inspection Photos  
Location Name: AD Jeffers 1  
Location ID: 318554



Photo 1 Location



Photo 2 Dead vegetation around the wellhead.

Inspection Photos  
Location Name: AD Jeffers 1  
Location ID: 318554



Photo 3 Dead vegetation around the well sign.

Photo 4 Ancillary equipment.