

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5436 From entrance to location



Photo # 5437 From entrance to location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022




Photo # 5438 Location



Photo # 5439 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5440 Location



Photo # 5441 Location

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5442 Location



Photo # 5443 Location



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5444 Holes in liner/liner needs maintenance



Photo # 5445 Holes in liner/liner needs maintenance



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5446 Hole in liner/liner needs maintenance



Photo # 5447 Hole in liner/liner needs maintenance

## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5448 Hole in liner/liner needs maintenance



Photo # 5449 Hole in liner/liner needs maintenance



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



**Photo # 5450 Small amount of staining in secondary containment**



**Photo # 5451 Small amount of staining in secondary containment**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5452 Small amount of staining near tank battery



Photo # 5453 Barbed wire fence needs maintenance/wildlife hazard



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



**Photo # 5454 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5455 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



**Photo # 5456 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5457 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



**Photo # 5458 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5459 Barbed wire fence needs maintenance/wildlife hazard**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



**Photo # 5460 Barbed wire fence needs maintenance/wildlife hazard**



**Photo # 5461 Open ended piping/available for entry by wildlife/wildlife hazard**



## Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC HANGS B Pad

Location ID: 336022



Photo # 5462 Dead deer in the interim area



Photo # 5463 Same dead deer in the interim area