

## Inspection/Audit Photos

Location: QB ENERGY JOLLEY-68S96W/3NESW (OK3 PAD)

Location ID: 334358

Date: 02/10/2025



Photo # 4618 Entrance to location




Photo # 4638 Location

## Inspection/Audit Photos

Location: QB ENERGY JOLLEY-68S96W/3NESW (OK3 PAD)

Location ID: 334358

Date: 02/10/2025



Photo # 4619 Location



Photo # 4629 Location



## Inspection/Audit Photos

Location: QB ENERGY JOLLEY-68S96W/3NESW (OK3 PAD)

Location ID: 334358

Date: 02/10/2025



Photo # 4637 Location



Photo # 4649 Location

## Inspection/Audit Photos

Location: QB ENERGY JOLLEY-68S96W/3NESW (OK3 PAD)

Location ID: 334358

Date: 02/10/2025



Photo # 4650 SW corner of location



Photo # 4651 SE corner of location



## Inspection/Audit Photos

Location: QB ENERGY JOLLEY-68S96W/3NESW (OK3 PAD)

Location ID: 334358

Date: 02/10/2025



Photo # 4652 NE corner of location



Photo # 4654 NW corner of location