

Inspection Photos

February 12th, 2024

Operator: Williford Resources - 96735

Location ID: 326324

Inspection Document #: 714001825

La Plata County, CO

Township: NWSE 23 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Macey 3
Location ID: 326324

2/12/25
229° SW



Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-07837

Inspection Photos
Location Name: Macey 3
Location ID: 326324



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of pump jack, no weeds or stained soils were observed.

API #: 067-07837

Inspection Photos
Location Name: Macey 3
Location ID: 326324



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of tank battery.

API #: 067-07837

2/12/25
82° E



Inspection Photos
Location Name: Macey 3
Location ID: 326324

2/12/25
171° S



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 5. Reference area composed of Rabbitbrush, Broom Snakeweed and James Galleta.

API #: 067-07837