

Inspection Photos

February 12th, 2024

Operator: Williford Resources - 96735

Location ID: 325650

Inspection Document #: 714001827

La Plata County, CO

Township: SENE 1 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Angelina 6
Location ID: 325650

2/12/25
65° NE



Photo 1. View of the well pad taken from the access point facing center.



Inspection Photos
Location Name: Angelina 6
Location ID: 325650



Photo 2. View of wellhead/pump jack, no stained soil was observed.

Inspection Photos
Location Name: Angelina 6
Location ID: 325650

2/12/25
353° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Interim reclamation area composed of Rabbitbrush, Broom Snakeweed and Sagebrush.

API #: 067-06772

Inspection Photos
Location Name: Angelina 6
Location ID: 325650

2/12/25
315° NW



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Rabbitbrush, Broom Snakeweed and James Galleta.

API #: 067-06772