

Inspection Photos
Location Name: Jacobucci 1
Location ID: 317917



Pic 1 GMR



Pic 2 Separator

Inspection Photos
Location Name: Jacobucci 1
Location ID: 317917



Pic 3 Tanks



Pic 4 Pump Jack / wellhead

Inspection Photos
Location Name: Jacobucci 1
Location ID: 317917



Pic 5 wellhead sign



Pic 6 ECD