



CA Completed

18395518361

Reference Number: 20250218-18395518361	Form Name: CA Completed
Submitter Name: Dana Pollack dana_pollack	Date Sent on Device: Feb 18, 2025 7:31:02 AM MST
Location:	

SITE DETAILS

Section 1

Pumper Route	Route E
State Name	CARNEY 4-5
Office Area	Rangely
Unique ID	11111
API # - FAC ID	05-103-09226
Property Type	Tank
Corrective Actions completed by?	2/14/2025
Inspection Date/Time	Feb 14, 2025 7:29:00 AM MST
CA identified from what source	COGCC
CA Issue	Tank needed bull plug
Image of CA Fixed	



LDAR CA Issue	No
Repair Verified	No

It is still leaking, attempt additional fixes to get below 500 PPM and verify again, record the highest PPM.

Comments - Please Explain CA Repaired	UGC installed bull plug to comply with ECEM inspection.
---------------------------------------	---