

Inspection Photos

API: 011-06174

Operator: CHOLLA PETROLEUM INC

Inspection Date: 2/14/2025

County: Bent



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the location. The location and access road has not been reclaimed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 2. Southwest side of the location facing northeast. This area consist of undesirable weeds and bare soils. Reclamation has not been performed.



Inspection Photos




Photo 3. South side of the location facing northeast. This area consist of undesirable weeds and bare soils. Reclamation has not been performed.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Southeast side of the location facing northwest. This area consist of undesirable weeds and bare soils. Reclamation has not been performed.



Inspection Photos




Photo 5. Facing along the northeast cut slope. There are bare soils that need to be revegetated.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 6. Facing west along the north side of the location. There are bare soils that need to be revegetated.

