

Inspection Photos

February 12th, 2024

Operator: Williford Resources - 96735

Location ID: 325553

Inspection Document #: 714001835

La Plata County, CO

Township: NWNW 24 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Spickelmier 1
Location ID: 325553



Photo 1. View of the well pad taken from the access point facing center. Well pad is dominated by weedy kochia.



Inspection Photos
Location Name: Spickelmier 1
Location ID: 325553



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. View of weedy kochia encroaching on pump jack equipment.

API #: 067-06594

Inspection Photos
Location Name: Spickelmier 1
Location ID: 325553



Photo 3. Tank battery equipment/sign.

2/12/25
203° SW

