

Inspection Photos

February 12th, 2024

Operator: Williford Resources - 96735

Location ID: 325619

Inspection Document #: 714001837

La Plata County, CO

Township: NENW 1 33N 12W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: M&M 6
Location ID: 325619



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos
Location Name: M&M 6
Location ID: 325619



Photo 2. Weedy debris observed around pump jack equipment.

Inspection Photos
Location Name: M&M 6
Location ID: 325619



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. View of tank equipment on location.

API #: 067-06719

Inspection Photos
Location Name: M&M 6
Location ID: 325619

2/12/25
249° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. View of interim reclamation composed of Sagebrush and Crested Wheatgrass.

API #: 067-06719

2/12/25
86° E

