

# Inspection Photos

February 13th, 2024

Operator: Catamount Energy Partners - 10464

Location ID: 440174

Inspection Document #: 714001845

La Plata County, CO

Township: SESE 19 34N 6W M

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources



**Photo 1.** View of the well pad taken from the access point facing center.





Inspection Photos  
Location Name: Elsa 34-6-19  
Location ID: 440174





Inspection Photos  
Location Name: Elsa 34-6-19  
Location ID: 440174



**Photo 3.** Weedy kochia debris lining location perimeter western and southern edges.



Inspection Photos  
Location Name: Elsa 34-6-19  
Location ID: 440174



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 4.** Interim reclamation area composed of Sagebrush, Crested Wheatgrass and Indian Ricegrass.

API #: 067-09922, 09945



Inspection Photos  
Location Name: Elsa 34-6-19  
Location ID: 440174

2/13/25  
123° SE



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

**Photo 5.** Reference area composed of Juniper, Sagebrush and Grama.

API #: 067-09922, 09945