

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



No sign at tank battery



Residue from previous staining.

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Open end tank valve. Debris.



Open to wildlife

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Unregistered open pit



Unregistered open pit

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Oily waste and stained soil



Oily waste and stained soil

Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938



Oily waste from partial cleanup



Staining

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Out of service. Unused equipment.



Location from Southwest entrance

**Antler Energy LLC
Ross-Government-USA 43-7
Location ID: 312938**



Location from North corner



Location from East corner