

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION

Receive Date:

04/23/2024

Document Number:

403766292

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: <u>47120</u>	Contact Person: <u>Erik Mickelson</u>
Company Name: <u>KERR MCGEE OIL & GAS ONSHORE LP</u>	Phone: <u>(970) 929-4306</u>
Address: <u>P O BOX 173779</u>	Fax: <u>()</u>
City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80217-3779</u>	Email: <u>Erik_Mickelson@oxy.com</u>

Identification Information

API Number: <u>05 - -</u>	ECMC Facility ID: <u>485209</u>	Initial Form 19 or 27 Document number: <u></u>
Facility Name: <u>LIZZY</u>	Facility Number: <u>8-36HZ</u>	Facility Type: <u>LOCATION</u>
Location QtrQtr: <u>SENE</u>	Section: <u>36</u>	Township: <u>1N</u>
	Range: <u>68W</u>	Meridian: <u>6</u>
	County: <u>WELD</u>	Field Name: <u></u>
Federal, Indian or State Lease Number: <u></u>		

Information Submitted By:

Company Name: <u>Absaroka Solutions</u>	Agent Name: <u>Jordan Fleming</u>	Title: <u>Environmental Professional</u>
Phone Number: <u>7202448469</u>	Email: <u>jordan.fleming@absarokasolutions.com</u>	

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: Unlined Lined Fenced Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: <u>772200</u>	Facility Name: <u>Child 235335</u>	Facility Type: <u>Domestic Well</u>
Location: QtrQtr: <u>NWNE</u>	Sec: <u>26</u>	Twp: <u>1N</u>
	Range: <u>68W</u>	Meridian: <u>6</u>
County Name: <u>BROOMFIELD</u>	Latitude: <u>40.029003</u>	Longitude: <u>-104.969925</u>

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: <u>118757</u>	Document Name: <u>Size of file in bytes: 28160</u>	File Name: <u>2024_02_15_Child 235335 Isotech SIW ECMC.xls</u>
SampleType: <u></u>	Matrix: <u></u>	
Facility ID: <u>772200</u>	Sample ID: <u>658224</u>	Sample Name: <u>Child 235335</u>
		Sample Date: <u>02/15/2024</u>
Collection Point: <u>Dom</u>	Matrix: <u>WATER</u>	Pre Post: <u>Voluntary Post drill</u>
Project Number: <u></u>	Remediation Number: <u></u>	Complaint Number: <u></u>
		NOAV Number: <u></u>
Inspection Number: <u></u>	Spill Number: <u></u>	Laboratory: <u>ISOTECH</u>
		Lab Sample ID: <u>911490</u>

Batch ID: 118758	Document Name: Size of file in bytes: 9387	File Name: 2024_02_15_Child 235335 SGS ECMC DRO.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 772200	Sample ID: 658225	Sample Name: Child 235335
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest
		Lab Sample ID: DA62098-1
Batch ID: 118760	Document Name: Size of file in bytes: 11562	File Name: 2024_02_15_Child 235335 Trip Blank SGS ECMC.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 772200	Sample ID: 658227	Sample Name: Child 235335
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest
		Lab Sample ID: DA62099-1
Batch ID: 118756	Document Name: Size of file in bytes: 35840	File Name: 2024_02_15_Child 235335 Isotech NG4 ECMC.xls
SampleType: _____	Matrix: _____	
Facility ID: 772200	Sample ID: 658223	Sample Name: Child 235335
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH
		Lab Sample ID: 911495
Batch ID: 118759	Document Name: Size of file in bytes: 27729	File Name: 2024_02_15_Child 235335 SGS ECMC.xlsx
SampleType: _____	Matrix: _____	
Facility ID: 772200	Sample ID: 658226	Sample Name: Child 235335
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest
		Lab Sample ID: DA62098-1
Batch ID: 118756	Document Name: Size of file in bytes: 35840	File Name: 2024_02_15_Child 235335 Isotech NG4 ECMC.xls
SampleType: _____	Matrix: _____	
Facility ID: 772200	Sample ID: 658222	Sample Name: Child 235335
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill
Project Number: _____	Remediation Number: _____	Complaint Number: _____
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH
		Lab Sample ID: 911495

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
772200	403766301	2024_02_15_Child 235335 Isotech NG4.pdf	Analytical Laboratory Report	PDF
772200	403766298	2024_02_15_Child 235335 Isotech SIW.pdf	Analytical Laboratory Report	PDF
772200	403766322	2024_02_15_Child_235335_Spigot_Wellhead.jpg	Photographs	JPG
772200	403766294	2024_02_15_Child 235335 Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
772200	403766316	2024_02_15_Child 235335 SGS.pdf	Analytical Laboratory Report	PDF
772200	403766320	2024_02_15_Child_235335_PrePostPurge.jpg	Photographs	JPG
772200	403766323	2024_02_15_Child_235335_Spigot_Wellhead_Loc.jpg	Photographs	JPG

772200	403766319	2024_02_15_Child_235335 _FS_ECMC.pdf	Field Data Report	PDF
--------	-----------	---	-------------------	-----

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system.	02/19/2025

Total: 1 comment(s)