

Inspection Photos

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325431

Inspection Document #: 714001847

La Plata County, CO

Township: NWSE 24 34N 7W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: State 01-24 1
Location ID: 325431



Photo 1. View of the well pad taken from the access point facing center.



API #: 067-06363



Inspection Photos
Location Name: State 01-24 1
Location ID: 325431

2/13/25
291° W



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 2. Interim reclamation area composed of Rabbitbrush, Sand Dropseed and Purple Threeawn.

API #: 067-06363

Inspection Photos
Location Name: State 01-24 1
Location ID: 325431



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Reference area composed of Rabbitbrush, Sand Dropseed and Purple Threawn.

API #: 067-06363