

Inspection Photos

February 13th, 2024

Operator: Simcoe LLC - 10749

Location ID: 325489

Inspection Document #: 714001860

La Plata County, CO

Township: SENE 32 34N 6W M

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Pine River 4-32 1
Location ID: 325489



Photo 1. View of the well pad taken from the access point facing center.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 067-06482

2/13/25
238° SW



Photo 2. Interim reclamation area composed of Rabbitbrush and Sand Dropseed.

Inspection Photos
Location Name: Pine River 4-32 1
Location ID: 325489



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 3. Erosion chanel/pit observed forming at the location access point.

API #: 067-06482

Inspection Photos
Location Name: Pine River 4-32 1
Location ID: 325489



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 4. Reference area composed of Gambel oak, Rabbitbrush, Four Winged Saltbush and Smooth Brome.

API #: 067-06482