

Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



Photo #1

State North Platte/O-26 Pad

CA: Unnecessary Equipment

Frac tank w/ spill pad

Drone photo

Top: North (N)



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos
January 29, 2025

Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



Photo #2

State North Platte/O-26 Pad

CA: Unnecessary Equipment

Frac tank w/ spill pad



Photo #3

State North Platte/O-26 Pad

CA: Unnecessary Equipment

Frac tank w/ spill pad



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos
January 29, 2025

Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



Photo #4

State North Platte/O-26 Pad

Drone photo

Top: North (N)



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos
January 29, 2025

Inspection Photos

Location Name: State North Platte/O-26 Pad

Location #: 434745



January 29, 2025 at 12:43 PM

+40.3633, -104.3984

233° SW

Weld County

Energy & Carbon Management Commission

Photo #5

State North Platte/O-26 Pad

Location Signage



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

State North Platte O-26 Pad Location ID #434745 Photos
January 29, 2025