

## Inspection Photos

Location Name: North Platte/T-23 Pad

Location #: 470863



Photo #1

North Platte/T-23 Pad 6: Wellsites

Producing | PR



Photo #2

North Platte/T-23 Pad

**CA: Unnecessary Equipment**

*Frac tank w/ spill pad*



Inspection Photos  
Location Name: North Platte/T-23 Pad  
Location #: 470863



Photo #3

North Platte/T-23 Pad 6: Wellsites

Producing | PR

Location sign



Photo #4

North Platte/T-23 Pad 6: Wellsites

Producing | PR

Pad, Wellsite(s) entrance

Location signage

