

Inspection Photos
Location Name: UPRR 43 Pan AM I 11
Location ID: 318454



Photo 1 Location.

Photo 2 Wellhead sign.

Inspection Photos
Location Name: UPRR 43 Pan AM I 11
Location ID: 318454



Photo 3 Wellhead valves are closed.



Photo 4 Electric panel & meter box are shut off.