

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Warren/15-9 (PI15)

Location ID: 334751

Date: 2/18/2025



Feb 18, 2025 at 10:56:49  
3393 Underwood Ln  
Parachute CO 81635  
United States

Location Overview – Photo #06680



Feb 18, 2025 at 10:58:14  
3393 Underwood Ln  
Parachute CO 81635  
United States

Location – Photo #06683

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Warren/15-9 (PI15)

Location ID: 334751

Date: 2/18/2025



Location – Photo #06685



Location – Photo #06686




## Inspection Photos


Location Name: CAERUS PICEANCE LLC, Warren/15-9 (PI15)

Location ID: 334751

Date: 2/18/2025



Location – Photo #06681



Location – Photo #06684

## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Warren/15-9 (PI15)

Location ID: 334751

Date: 2/18/2025



Location – Photo #06687



Wildlife Entry Hazard – Photo #06688





## Inspection Photos

Location Name: CAERUS PICEANCE LLC, Warren/15-9 (PI15)

Location ID: 334751

Date: 2/18/2025



Wildlife Entry Hazard – Photo #06689



Wildlife Entry Hazard – Photo #06690

## Inspection Photos


Location Name: CAERUS PICEANCE LLC, Warren/15-9 (PI15)

Location ID: 334751

Date: 2/18/2025



Wildlife Entry Hazard – Photo #066910



Location – Photo #06692