

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 42A-35-692 Pad

Location ID: 335020



Photo # 7398 From entrance to location




Photo # 7399 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 42A-35-692 Pad

Location ID: 335020



Feb 19, 2025 at 1:40:39 PM
CO

Photo # 7400 Location



Feb 19, 2025 at 1:41:54 PM
CO

Photo # 7401 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 42A-35-692 Pad

Location ID: 335020



Photo # 7402 Mechanical condition – possible valve leak



Photo # 7403 Mechanical condition – possible valve leak

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 42A-35-692 Pad

Location ID: 335020



Photo # 7404 Mechanical condition – possible valve leak



Photo # 7405 Mechanical condition – possible valve leak

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC CIRCLE B LAND 42A-35-692 Pad

Location ID: 335020



Photo # 7406 Mechanical condition – possible valve leak