

Final Reclamation and Stormwater Inspection

February 12, 2025

Operator: PDC ENERGY INC - 69175

Location ID: 320251

Well Name: ADAMS AGGREGATE #2

Inspection Document #: 718600281

Adams County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: ADAMS AGGREGATE #2
Location ID: 320251



Photo 1. Google earth aerial photo taken 05/2018 prior to decommissioning. A piece of equipment is located to the east of the southern separator.



Inspection Photos
Location Name: ADAMS AGGREGATE #2
Location ID: 320251



Photo 2. Google earth aerial photo taken 09/2019. The pad is recontoured except for the area around the piece of equipment which appears to remain in place.



Inspection Photos
Location Name: ADAMS AGGREGATE #2
Location ID: 320251



Photo 3. Operator supplied imagery “South of Tank Battery Disturbance Facing North” attached to Doc ID #404012872. It appears the equipment remains in place (red circle).

