

State of Colorado
Energy & Carbon Management Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

ECMC RECEPTION

Receive Date:

06/05/2024

Document Number:

403813305

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 47120 Contact Person: Erik Mickelson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (970) 929-4306
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - ECMC Facility ID: 323420 Initial Form 19 or 27 Document number:
Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION
Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6
County: WELD Field Name: WATTENBERG
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Solutions Agent Name: Jordan Fleming Title: Environmental Professional
Phone Number: 7202448469 Email: jordan.fleming@absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 752922 Facility Name: Hochmiller_84411 Facility Type: Commercial
Location: QtrQtr: NWNE Sec: 32 Twp: 3N Range: 65W Meridian: 6
County Name: WELD Latitude: 40.188001 Longitude: -104.683636

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 119699 Document Name: Size of file in bytes: 13314 File Name: 2024_03_11_Hochmiller 84411--A Isotech NG4
ECMC.xlsx
SampleType: Matrix:
Facility ID: 752922 Sample ID: 659192 Sample Name: Hochmiller 84411--A Sample Date: 03/11/2024
Collection Point: Dom Matrix: WATER Pre Post: Voluntary Post drill
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 915117

Batch ID: 119699		Document Name: Size of file in bytes: 13314		File Name: 2024_03_11_Hochmiller 84411--A Isotech NG4 ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 659191	Sample Name: Hochmiller 84411--A		Sample Date: 03/11/2024	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 915117		

Batch ID: 119617		Document Name: Size of file in bytes: 9392		File Name: 2024_03_11_Hochmiller 84411--A SGS ECMC DRO.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 659108	Sample Name: Hochmiller 84411--A		Sample Date: 03/11/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA62884-1		

Batch ID: 119615		Document Name: Size of file in bytes: 11591		File Name: 2024_03_11_Hochmiller 84411--A Trip Blank SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 659106	Sample Name: Hochmiller 84411--A		Sample Date: 03/11/2024	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA62886-1		

Batch ID: 119618		Document Name: Size of file in bytes: 28160		File Name: 2024_03_11_Hochmiller 84411--A Isotech SIW ECMC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 659109	Sample Name: Hochmiller 84411--A		Sample Date: 03/11/2024	
Collection Point: Dom	Matrix: GAS	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 915112		

Batch ID: 119616		Document Name: Size of file in bytes: 27206		File Name: 2024_03_11_Hochmiller 84411--A SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 659107	Sample Name: Hochmiller 84411--A		Sample Date: 03/11/2024	
Collection Point: Dom	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA62884-1		

Batch ID: 119621		Document Name: Size of file in bytes: 11590		File Name: 2024_03_11_Hochmiller 84411--A Field Blank SGS ECMC.xlsx	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 659112	Sample Name: Hochmiller 84411--A		Sample Date: 03/11/2024	
Collection Point: TB	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA62885-1		

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
752922	403813333	2024_03_11_Hochmiller_84411_A_Spigit.jpg	Photographs	JPG
752922	403814746	2024_03_11_Hochmiller 84411--A Isotech NG4.pdf	Analytical Laboratory Report	PDF

752922	403813332	2024_03_11_Hochmiller_84411_A_PrePostPurge.jpg	Photographs	JPG
752922	403813331	2024_03_11_Hochmiller_84411_A_FS_ECMC.pdf	Field Data Report	PDF
752922	403813310	2024_03_11_Hochmiller_84411--A Field Blank SGS.pdf	Analytical Laboratory Report	PDF
752922	403813329	2024_03_11_Hochmiller_84411--A Trip Blank SGS.pdf	Analytical Laboratory Report	PDF
752922	403813330	2024_03_11_Hochmiller_84411--A SGS.pdf	Analytical Laboratory Report	PDF
752922	403813328	2024_03_11_Hochmiller_84411--A Isotech SIW.pdf	Analytical Laboratory Report	PDF
752922	403813336	2024_03_11_Hochmiller_84411_A_Wellhead.jpg	Photographs	JPG
752922	403813335	2024_03_11_Hochmiller_84411_A_Spigot_Wellhead_Loc.jpg	Photographs	JPG

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

User Group	Comment	Comment Date
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system. Sample 659192 Sample Type was changed from "Air Sparge" to "Ground Water".	02/20/2025
Total: 1 comment(s)		