

Inspection Photos

Loc: 307664

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 2/19/2025

County: LAS ANIMAS



Inspection Photos



Photo 1. Facing northeast toward the access road.



Inspection Photos



Photo 2. Facing southwest toward the location.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:307664 | Date: 2/19/2025

Inspection Photos



Photo 3. Facing southwest along the fill slope which is stabilized with vegetation and other BMP's.

